

Premium Cable Joint Kits



Cable Joint Selection Chart

main cable (mm ²)	number of cores	KIT REQUIRED		max branch cable (up to 4 core)
		through joint	branch joint	
1.5	2	CM0+C	CU0+C	2.5mm ²
1.5	3	CM0+C	CU0+C	2.5mm ²
1.5	4	CM0+C	CU0+C	2.5mm ²
2.5	2	CM0+C	CU0+C	2.5mm ²
2.5	3	CM0+C	CU0+C	2.5mm ²
2.5	4	CM0+C	CU0+C	2.5mm ²
4	2	CM0+C	CU1+C	6mm ²
4	3	CM0+C	CU1+C	6mm ²
4	4	CM0+C	CU1+C	6mm ²
6	2	CM0+C	CU1+C	6mm ²
6	3	CM0+C	CU1+C	6mm ²
6	4	CM0+C	CU1+C	6mm ²
10	2	CM0+C	CU2+C	25mm ²
10	3	CM1+C	CU2+C	25mm ²
10	4	CM1+C	CU2+C	25mm ²
16	2	CM1+C	CU2+C	25mm ²
16	3	CM1+C	CU2+C	25mm ²
16	4	CM1+C	CU2+C	25mm ²
25	2	CM1+C	CU2+C	25mm ²
25	3	CM1+C	CU2+C	25mm ²
25	4	CM2+C	CU3+C	25mm ²
35	2	CM2+C	CU3+C	35mm ²
35	3	CM2+C	CU3+C	35mm ²
35	4	CM3+C	CU3+C	35mm ²

main cable (mm ²)	number of cores	KIT REQUIRED		max branch cable (up to 4 core)
		through joint	branch joint	
50	2	CM2+C	CU3+C	35mm ²
50	3	CM3+C	CU3+C	35mm ²
50	4	CM3+C	CU3+C	35mm ²
70	2	CM3+C	CU4+C	35mm ²
70	3	CM3+C	CU4+C	35mm ²
70	4	CM3+C	CU4+C	35mm ²
95	2	CM3+C	CU4+C	35mm ²
95	3	CM3+C	CU4+C	35mm ²
95	4	CM3+C	CU4+C	35mm ²
120	2	CM3+C	CU5+C	35mm ²
120	3	CM4+C	CU5+C	35mm ²
120	4	CM4+C	CU5+C	35mm ²
150	2	CM4+C	CU5+C	35mm ²
150	3	CM4+C	CU5+C	35mm ²
150	4	CM5+C	CU5+C	35mm ²
185	2	CM4+C	CU5+C	35mm ²
185	4	CM6+C	CU5+C	35mm ²
240	2	CM4+C	-	-
240	2	CM5+C	-	-
240	3	CM6+C	-	-
240	4	CM6+C	-	-
300	2	CM5+C	-	-
300	3	CM6+C	-	-
400	2	CM6+C	-	-

